

Triton Systems, Inc. ADA Compliance Statement

15 December 2000

Affected Models: 95XX, 96XX, Scrip, SuperScrip, Mako

The Americans with Disabilities Act of 1990, Title III, 42 U.S.C. §§ 12181-12189 passed July 28, 1991, and the subsequent regulations issued by the United States Department of Justice provides comprehensive civil rights protection from discrimination by private entities in places of public accommodation and commercial facilities.

Section 4.34 of Title III addresses Automatic Teller Machines. As a general rule where Automated Teller Machines (ATMs) are provided, each ATM shall comply with the requirement of 4.34 except where two or more are provided at a location. Then only one must comply.

When installed properly (according to the manufacturer's specifications), Triton's Dispensers (Model 95XX Series, Model 96XX Series, Scrip, SuperScrip, Mako) are in full compliance with the Americans with Disabilities Act, Title III, Section 4.34. The following sections from Title III apply to Triton as the manufacturer of the ATM.

4.27.4 Operation: Controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. The force required to activate controls shall be no greater than 5 lb.

4.2.5 Forward Reach: If the clear floor space only allows forward approach to an object, the maximum high forward reach allowed shall be 48 inches (1220mm) above the floor.

4.2.6 Side Reach: If the clear floor space allows parallel approach by a person in a wheelchair, the maximum high side reach allowed shall be 54 inches (1370MM) and the low side reach shall be no less than 9 inches (230mm) above the floor.

Braille: Braille characters are molded into the keypad buttons on the Mako, SuperScrip and 96XX model Cash Dispensers and are standard on all of these Cash Dispenser models.

Within Section 4.34 of Title III of the American with Disabilities Act are other regulations and specifications that apply to the locations where ATMs are installed or will be installed. This information will be important for Triton Systems' distributors. This information is available at your request from Triton Systems.